

DELL Laptop

Check this out immediately if you have a DELL Laptop bought or serviced during the stated period;

Go to <https://www.dellbatteryprogram.com/> for interactive details and what to do.

Dell has identified a potential issue associated with certain batteries sold with Dell Latitude™, Inspiron™, XPS™ and Dell Precision Mobile Workstation™ notebook computers. In cooperation with the U.S. Consumer Product Safety Commission and other regulatory agencies, Dell is voluntarily recalling certain Dell-branded batteries with cells manufactured by Sony and offering free replacements for these batteries. Under rare conditions, it is possible for these batteries to overheat, which could pose a risk of fire.

Potentially affected batteries were sold with the following models of Dell notebook computers or separately as secondary batteries:

Latitude: D410, D500, D505, D510, D520, D600, D610, D620, D800, D810

Inspiron: 500M, 510M, 600M, 700M, 710M, 6000, 6400, 8500, 8600, 9100, 9200, 9300, 9400, E1505, E1705

Precision: M20, M60, M70, M90

XPS: XPS, XPS Gen2, XPS M170, XPS M1710

In addition, these batteries may have also been provided in response to service calls. The batteries were shipped to customers between April 1, 2004 and July 18, 2006. The words "DELL" and "Made in Japan" or "Made in China" or "Battery cell made in Japan, Assembled in China" are printed on the back of the batteries. If your battery does not reflect one of these markings it is not part of this recall, and you may exit the site.